

# Paint, rust and underseal removal.



1



2



3



4

**1** & **2** Find the shell and strip it down. This is a Volvo P1800.

**3** SPL's unique chemical process will remove the paint, rust, underseal and filler.

**4** You repair it and SPL clean it again.


**5** The whole shell is then zinc phosphate immersed in electrophoretic paint and cured at 185°C. Corrosion protected inside and out.



5

A unique chemical process, no blasting, no stress, no mess. The best available process for preparation and restoration.

**Tel: 01384 242010**



[www.surfaceprocessing.co.uk](http://www.surfaceprocessing.co.uk) [sales@surfaceprocessing.co.uk](mailto:sales@surfaceprocessing.co.uk)

Paint Stripping | Degreasing | Derusting | Electrophoretic Coating | Shells | Panels | Parts